

# PROGRESSIVE STAGE PRESS STEEL SHOT CHARGE BAR - MEC RELOADING 7/8OZ #5-#6 SHOT PROGRESSIVE STAGE STEEL SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

Steel Shot charge bar is designed for progressive reloaders. Available to load from 7/8 oz to 1-1/2 oz. of shot and BB sizes down to #6.



## Attributes

- Name: [MEC RELOADING 7/8OZ #5-#6 SHOT PROGRESSIVE STAGE STEEL SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019426
- Mfr. No.: 50207856
- Size: 7/8 oz
- Delivery weight: 0.236kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489013048

## Item details

Made in USA

# Table of Contents

- Startpage
- Safety Instruction Guide for Progressive Stage Press Steel Shot Charge Bar
- About Us

# Safety Instruction Guide for Progressive Stage Press Steel Shot Charge Bar

## Introduction

Thank you for choosing the Progressive Stage Press Steel Shot Charge Bar from MEC Reloading. This product is designed for progressive reloaders, allowing you to load shot from 7/8 oz to 11/2 oz, including BB sizes down to #6. To ensure your safety and the safe operation of this product, please read this guide carefully.

## General Safety Guidelines

- Always follow the manufacturer's instructions for the safe use of the product.
- Ensure that the product is used only for its intended purpose.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly check for product recalls or safety updates via the EU Safety Gate platform.
- Report any unsafe products or accidents to the relevant authorities.

## Specific Safety Precautions for Use

- Use the charge bar only with compatible reloading presses.
- Inspect the charge bar for any signs of damage or wear before each use.
- Do not overload the charge bar beyond the specified limits (7/8 oz to 11/2 oz).
- Wear appropriate safety gear, such as eye protection, when operating the reloading press.
- Ensure that your workspace is clean and free of distractions while using the charge bar.
- Store the charge bar in a safe place when not in use to prevent accidental injury.

## Instructions for Installation and Usage

### 1. Installation:

- Ensure that your reloading press is turned off and unplugged.
- Remove any existing charge bar from the press if applicable.
- Align the Progressive Stage Press Steel Shot Charge Bar with the mounting points on your reloading press.
- Securely fasten the charge bar according to the manufacturer's instructions.

### 2. Usage:

- Set the desired shot weight on the charge bar (between 7/8 oz to 11/2 oz).
- Fill the charge bar with the appropriate type of shot.
- Follow the reloading press's operational guidelines to load the shot into the shell.
- Monitor the loading process closely to ensure that everything is functioning correctly.

## Disposal Instructions

- Dispose of any packaging materials in accordance with local waste disposal regulations.
- If the charge bar is damaged beyond repair, consider recycling the metal components where possible.
- Do not dispose of the charge bar in regular household waste if it is still usable; consider donating it or passing it on to another user.

## Contact Information for Further Support

For any inquiries regarding safety, usage, or product support, please refer to the manufacturer's contact information. It is essential to have a reliable point of contact for any safety concerns or questions you may have.

Thank you for prioritizing safety while using the Progressive Stage Press Steel Shot Charge Bar. Your adherence to these guidelines helps ensure a safe and enjoyable reloading experience.

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)