

PROGRESSIVE STAGE PRESS STEEL SHOT CHARGE BAR - MEC RELOADING 1-1/4OZ BB-#2 SHOT PROGRESSIVE STAGE STEEL SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

Steel Shot charge bar is designed for progressive reloaders. Available to load from 7/8 oz to 1-1/2 oz. of shot and BB sizes down to #6.



Attributes

- Name: [MEC RELOADING 1-1/4OZ BB-#2 SHOT PROGRESSIVE STAGE STEEL SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019430
- Mfr. No.: 502114BB2
- Size: 1-1/4 oz
- Delivery weight: 0.227kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489016964

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for PROGRESSIVE STAGE PRESS STEEL SHOT CHARGE BAR
- About Us

Safety Instruction Guide for PROGRESSIVE STAGE PRESS STEEL SHOT CHARGE BAR

Introduction

Thank you for choosing the PROGRESSIVE STAGE PRESS STEEL SHOT CHARGE BAR by MEC RELOADING. This product is designed for progressive reloaders and allows for loading shot weights from 7/8 oz to 11/2 oz, including BB sizes down to #6. To ensure safe and efficient use of this product, please read and follow the safety instructions outlined in this guide.

General Safety Guidelines

- Always read the instruction manual before using the product.
- Use the product only as intended and in accordance with the manufacturer's specifications.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly check for any signs of wear or damage to the product.
- In case of any malfunction or damage, cease use immediately and consult a professional.
- Report any unsafe product experiences to the relevant authorities.

Specific Safety Precautions for Use

- Ensure that the working area is wellventilated and free from flammable materials.
- Wear appropriate personal protective equipment (PPE), including safety glasses and gloves, while using the product.
- Avoid contact with moving parts during operation to prevent injury.
- Do not overload the charge bar beyond the specified weight limits.
- Maintain a safe distance from the product while it is in operation to avoid potential hazards.
- Ensure that all components are securely attached before use.

Instructions for Installation and Usage

1. Installation

- Unpack the charge bar and check for all components.
- Ensure that the charge bar is clean and free from debris.
- Attach the charge bar to the reloading press securely, following the manufacturer's instructions.
- Adjust the charge bar settings according to the desired shot weight.

2. Usage

- Load the appropriate amount of steel shot into the charge bar.
- Follow the reloading press instructions to operate the press safely and effectively.
- Monitor the operation regularly to ensure everything is functioning correctly.
- After use, clean the charge bar to prevent buildup of materials.

Disposal Instructions

- Dispose of any packaging materials in accordance with local waste management regulations.
- If the product is no longer usable, consult local guidelines for the disposal of metal and plastic components.
- Do not dispose of the product in household waste unless specified by local regulations.

Contact Information for Further Support

For safety inquiries or product support, please refer to the contact information provided with your product or visit the manufacturer's website.

By following these guidelines, you can ensure a safe and efficient experience with the PROGRESSIVE STAGE PRESS STEEL SHOT CHARGE BAR. Always prioritize safety and report any concerns regarding product safety to the appropriate authorities. Thank you for your attention and safe reloading!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk