

ZERO STORAGE BLOCK

ZERO STORAGE BLOCK The first in a line of ARCA-mounted accessories for the rear of your ZERO, the ZERO Storage Block is the perfect storage solution for the small tools, shellholders, and disparate parts that Area 419 are sure are around your press. Featuring a hole specifically for your ZERO torque wrench, and a magnet for attaching other tools, they think it'll help to clean up your bench and organize your gear. This tray is also ambidextrous, and can be hung from either side of the ZERO with full functionality.



Attributes

- Name: ZERO STORAGE BLOCK
- Manufacturer: AREA 419
- Product no.: 430112803
- Mfr. No.: 419-ZERO-SB
- Delivery weight: 0.907kg
- Shipping height: 51mm
- Shipping width: 127mm
- Shipping length: 203mm
- UPC: 810080180987

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [English: ZERO Storage Block Safety Instruction Guide](#)

ZERO Storage Block Safety Instruction Guide

Introduction

Thank you for choosing the ZERO Storage Block by AREA 419. This product is designed to provide a practical storage solution for your small tools, shellholders, and other components associated with your ZERO press. To ensure safe and effective use of the ZERO Storage Block, please read the following safety instructions carefully.

General Safety Guidelines

- Ensure that the ZERO Storage Block is used only for its intended purpose as a storage accessory for tools and parts related to the ZERO press.
- Regularly inspect the ZERO Storage Block for any signs of wear or damage. Do not use if damaged.
- Keep the ZERO Storage Block out of reach of children and vulnerable individuals to prevent accidents.
- Avoid placing heavy or oversized items in the ZERO Storage Block that may compromise its integrity or stability.
- Use the ZERO Storage Block in a welllit environment to avoid accidents while accessing tools and parts.
- Follow all relevant local regulations regarding the use and storage of tools and accessories.

Specific Safety Precautions for Use

- Ensure that all tools and parts stored in the ZERO Storage Block are dry and free from any hazardous substances.
- Do not overload the ZERO Storage Block beyond its recommended capacity.
- When using the magnet feature, ensure that it is securely attached to prevent tools from falling.
- Be cautious when using sharp tools; always store them securely within the ZERO Storage Block.
- If using the torque wrench hole, ensure that the wrench is properly fitted and secure before use.
- Always remove any tools from the ZERO Storage Block carefully to avoid dropping them.

Instructions for Installation and Usage

1. Installation:

- Choose a suitable location on your ZERO press for mounting the ZERO Storage Block.
- Ensure that the surface is clean and free from debris before installation.
- Hang the ZERO Storage Block from either side of the ZERO press, ensuring it is securely attached.
- Confirm that the ZERO Storage Block is stable and does not wobble before placing any items in it.

2. Usage:

- Place small tools, shellholders, and parts in the designated areas of the ZERO Storage Block.
- Use the hole for the torque wrench to store it securely when not in use.
- Utilize the magnet feature to attach other tools for easy access.
- Regularly organize and clean the ZERO Storage Block to maintain its functionality and appearance.

Disposal Instructions

- Dispose of the ZERO Storage Block responsibly at the end of its life cycle.
- Check local regulations for proper disposal methods for plastic and other materials.
- Do not dispose of the ZERO Storage Block in general waste if it can be recycled.
- Consider donating or repurposing the product if it is still in usable condition.

Contact Information for Further Support

For any questions or concerns regarding the ZERO Storage Block, please reach out to the manufacturer or your place of purchase for assistance. Always refer to the latest safety guidelines and updates regarding this product.

Thank you for taking the time to read this safety instruction guide. Your safety and satisfaction are our top priorities. Enjoy using your ZERO Storage Block!